PACSystems* RX3i IC695RMX228-ABAA

Redundancy Memory Xchange Module

GFK-2905A July 2015

The PACSystems^{*} Redundancy Memory Xchange (RMX) module operates as a node on a reflective memory network or as a dedicated link between CPUs in an RX3i Hot Standby CPU Redundancy system. When the RMX is not being used as a link in a redundancy system, it is functionally identical to the IC695CMX128 module. Each node in the network can be any reflective memory device that is compatible with the 5565 family. Whenever data is written to one node, all nodes on the network are automatically updated with the new data.

When used as a node on a reflective memory network, the RMX module provides deterministic sharing of data among PLCs and other computing devices on a high-speed fiber-optic network. A reflective memory network can contain up to 256 nodes.

Each node in the reflective memory network is connected in a daisychained loop using fiber-optic cables. The transmitter of the first node is tied to the receiver of the second. The transmitter of the second node is tied to the receiver of the third node, and so on, until the loop is completed at the receiver of the first node.

When used in a CPU redundancy system, the RMX modules provide a path for transferring data between the two redundancy CPUs in the redundant system. A complete communications path consists of one RMX in the primary unit, one RMX in the secondary unit, and two high-speed fiber-optic cables connecting them to each other. This must be a two-node ring: no other reflective memory nodes are allowed to be part of this fiber-optic network.

GE Intelligent Platforms *strongly recommends* two redundancy links (a total of four RMX modules) be configured and installed. Optionally, systems can be configured for a single redundancy link (a total of two RMX modules).

When the RMX is being used as link in a redundancy system, it cannot be used as a general-purpose Memory Xchange module. For details on the operation of a PACSystems CPU redundancy system, refer to GFK-2308, PACSystems Hot Standby CPU Redundancy User's Manual.

A PACSystems RX3i main rack supports a maximum of six Memory Xchange modules in any combination of RMX128, RMX228, and CMX128 modules. A maximum of two RMX modules can be configured as redundancy communication links.



^{© 2015} General Electric Company. All Rights Reserved.

^{*} Indicates a trademark of General Electric Company and/or its subsidiaries. All other trademarks are the property of their respective owners.

GFK-2905A

Features

- PACSystems RX3i single slot form factor.
- 128 Mbytes reflective memory.[†]
- Software configuration of all node parameters (no jumper or switch settings required).[†]
- High-speed easy-to-use 2.12 Gbaud fiber-optic network.
- No RX3i CPU processing required to operate the network.
- When not used in a Redundant pair, network-compatible with VMIC 5565 family of reflective memory devices, including the RX7i CMX/RMX module (hub required when mixing Multi Mode and Single mode modules on the same network).
- Connection with single-mode fiber up to 10 km/6.2 mi. A single mode card cannot directly connect to a multimode card.
- Dynamic packet sizes of 4 to 68 bytes, controlled by the RMX128/RMX228 module when configured to
 operate as a CMX128 module.
- Programmable module interrupt output.
- Four general-purpose network interrupts with 32 bits of data each.^{†o}
- Network error detection.
- Up to 256 nodes per network.[†]
- Redundant transfer mode operation. This optional mode reduces the chance of a data packet being dropped from the network.[†]
- Configurable network memory offset allows you to assign nodes on a network to groups according to the 16MB segment in the network address space that they use.[†]

The RMX128/RMX228 module must be located in an RX3i Universal Backplane. The module can be hotinserted and removed following the instructions in the *PACSystems RX3i System Manual* (GFK-2314).

[†]Not available when operating as a redundancy link in a CPU redundancy system.

Specifications

| Packet size | Dynamic, automatically controlled by RMX128/RMX228 module | |
|--------------------------|---|--|
| User memory | 128MB SDRAM | |
| Input power | 580 mA @ +3.3 VDC | |
| (from RX3i power supply) | 220 mA @ +5 VDC | |
| Connectors | Fiber-optic LC type, conforms to IEC 61754-20 | |
| | Insertion loss: refer to cable/connector specifications | |
| | Return loss: refer to cable/connector specifications | |

Refer to the PACSystems RX3i System Manual (GFK-2314) for product standards and general specifications.

3

Related Publications

Available at <u>www.ge-ip.com/support</u>

PACSystems CPU Reference Manual (GFK-2222) PACSystems RX3i System Manual (GFK-2314E) or later PACSystems Memory Xchange Modules User's Manual (GFK-2300E) or later PACSystems RX3i Ethernet NIU User's Manual (GFK-2439) PACSystems Hot Standby CPU Redundancy User's Guide (GFK-2308J) or later

Ordering Information

| Description | Catalog Number |
|---|---|
| Reflective Memory Xchange Module for RX3i | IC695RMX228 |
| Single Mode Fiber-optic Cables | Bought separately and not furnished by GE |
| Reflective Memory Hub | VMIACC-5595 |

General Conditions for Safe Use

This product is intended to be for use with the RX3i system. Its components are considered open equipment [having live electrical parts that may be accessible to users] and must be installed in a protective enclosure or incorporated into an assembly that is manufactured to provide safety. As a minimum, the enclosure or assembly shall provide a degree of protection against solid objects up to 12mm (e.g. fingers). This equates to a NEMA/UL Type 1 enclosure or an IP20 rating (IEC60529) providing at least a pollution degree 2 environment.

Installation in Hazardous Locations

The following information is for products bearing the UL marking for Hazardous Areas, or ATEX marking for explosive atmospheres:

Class 1 Division 2 Groups ABCD

- This equipment shall be installed in an ultimate enclosure suitable for the environment that is only accessible with the use of a tool.
- Suitable for use in Class I, Division 2, Groups A, B, C and D Hazardous Locations, or nonhazardous locations only.



EXPLOSION HAZARD - Substitution of components may impair suitability for class I, division 2.

EXPLOSION HAZARD – The usb port is only for use in nonhazardous locations, do not use unless area is known to be non-hazardous.



When in hazardous locations, turn off power before replacing or wiring modules; and

DO NOT connect or disconnect equipment unless power has been switched off or the area is known to be nonhazardous.

GFK-2905A

ATEX Zone 2

This product must be mounted in an enclosure certified in accordance with EN60079-15 for use in Zone 2, Group IIC and rated IP54. The enclosure shall only be able to be opened with the use of a tool .

EMC Installation Requirements

- To meet EN 55011 and FCC Class A radiated emissions, the Control system in which the IC695RMX128/RMX228 module is used shall be mounted in a metal enclosure
- Applications using this module outside a grounded metal enclosure may experience RF interference.



When installing, operating, or maintaining the IC695RMX128/RMX228, personnel must ensure any electrostatic charge is discharged through the use of a grounded ESD strap or other means.

Release History

| Release | Firmware Version | Date | Comments |
|------------------|---------------------|-----------|---|
| IC695RMX228-ABAA | 2.00 | July 2015 | Revision ABAA enhances the design's resistance to the rare condition of corruption during a memory read (seen by user as a broken redundant link on an RMX228) from occurring. |
| IC695RMX228-AAAA | 2.00 | June 2014 | Initial release for IC695RMX228 |

Important Product Information for this Release

Upgrades



Do not install firmware versions earlier than 2.00. This will render the unit inoperable and will require the unit be returned to the factory.

Functional Compatibility

The RMX requires the following versions for configuration and operation.

| Subject | Description |
|---------------------------------|---|
| Programmer Version Requirements | PME version 8.5 SIM1 or later must be used for compatibility with the RMX228 module. |
| RX3i CPU | RX3i CPU firmware 8.15 (or later) is required to be used with RMX228 hardware version –AA and firmware version 2.00. |
| | PACSystems RX3i CRU320 is required for use in a redundancy system. |
| RMX228 Versions | Firmware versions earlier than 2.00 are not compatible with any of the RMX228 hardware versions. |
| Rack Location | The RMX128/RMX228 must be located in the main RX3i rack. IC695RMX128/RMX228 modules require a PCI backplane, which is not available on IC694CHSxxx expansion bases. |

Problems Resolved by Firmware Release 2.00

| Subject | Description |
|-----------------------------|--|
| Memory Read Data Corruption | Revision AAAA enhances the design's resistance to the rare condition of corruption during a memory read (seen by user as a broken redundant link on an RMX228) from occurring. |

Restrictions and Open Issues in this Release

| Subject | Description |
|---|---|
| RX3i RMX/CMX modules require grounded ESD strap for EMC Installation | When installing, operating, or maintaining the IC695RMX128/RMX228, personnel must ensure any electrostatic charge is discharged through the use of a grounded ESD strap or other means to meet IEC-61000-4-2 (ESD) requirements. A direct electrostatic discharge event of 4 kV or higher applied to the metal optical transceiver housing may result in a lights out module requiring a power cycle to recover. |
| RX3i RMX and CMX modules require a metal enclosure to meet radiated emissions requirements. | For installation requirements, refer to the section, <u><i>EMC Installation</i></u> <u><i>Requirements</i></u> . |
| RX3i CMX/RMX does not disable transmitter when the CPU goes to Stop/Halt mode. | For IC695CMX128, IC695RMX128, and IC695RMX228 modules not used as redundancy links, the automatic transmitter disable feature currently does not work correctly when a controller goes to Stop/Halt mode. When the CPU goes to Stop/Halt mode or fails and the automatic transmitter disable feature is enabled, the fiber-optic transmitter should be turned off, breaking the reflective memory link. When the feature is disabled, the transmitter remains ON and the reflective memory link will not be broken. If this feature is enabled, the automatic transmitter disable feature does not work when the CPU goes into Stop/Halt mode (such as after a software watchdog trip or multi-bit ECC error detection) leaving the fiber- optic transmitter ON. The fiber-optic transmitter is properly disabled if the CPU fails or is lost (for instance the CPU hardware is removed, the CPU experiences a hardware watchdog event, or displays a blink code such as |
| | a page fault). This user-configurable feature is enabled by default. The feature may be disabled by clearing bit 12 with a BUS_WRITE to region 3, offset 0x440. |

GFK-2905A

| Subject | Description |
|--|--|
| The LCSR status bit is not turning ON after LISR turns ON when Interrupt (Sync Loss) is generated. | When a sync loss condition is detected the LISR bit is latched ON but the LCSR sync loss bit is not latched ON (that is, it remains OFF). To check the sync loss status, monitor the sync loss bit in the LISR register instead of the LCSR sync loss bit. |
| SVC_REQ 17 is not supported | SVC_REQ 17 is not supported to mask or unmask module interrupts on RX3i CPUs. There is currently no way to identify which module interrupt should be masked on RX3i. For RX7i this was handled by a table of values, but this table of values is invalid on RX3i. Instead the customer should simply turn off interrupts using the normal interrupt disabling mechanism as described in the user's manual. |

Operational Notes

| Bad Data Interrupt | To prevent continuous interrupts when the Bad Data Interrupt is enabled, you may want to temporarily set bit 8 in the LIER to 0 when a sync loss condition is detected. If your application is also using the Sync Loss Interrupt, you may also want to temporarily set bit 11 in the LIER to zero when the sync loss condition is detected. You can then re-enable the Bad Data Interrupt (and Sync Loss Interrupt if it was also disabled) when the |
|--------------------|--|
| | sync loss condition has been corrected. |